



# Information of PSC Trends

- ☐ USCG
- ☐ PARIS MOU
- ☒ TOKYO MOU
- ☐ OTHER



No. PSC-2023-02

**Subject: Information of PSC Trends (Guangzhou, Shanghai, China)**

## 1. Guangzhou

○ Please be informed that we had received from Guangzhou PSCO that recently they will enhance and focus on the problem of **davit launched lifeboat's bottom drain valve plug condition**. It is needed to pre-check their vessel's boat bottom plug condition, and rectify by themselves in order to prevent the detention due to this situation while their vessel calling to all the terminals at Guangzhou.

## 2. Related Photo

	Ball Cover Missing
	Ball Size small than hole



## Information of PSC Trends

- ☐ USCG
- ☐ PARIS MOU
- ☒ TOKYO MOU
- ☐ OTHER

No. PSC-2023-02

### 3. Shanghai

○ Please be informed that we have already informed that the following items are normally inspected during PSC Inspection in Shanghai Area, but the same deficiencies are still identified during PSC Inspection. So, It is needed to pre-check their vessel and rectify by themselves in order to prevent the detention due to this situation while their vessel calling to all the terminals at Shanghai.

- Local Fire Fighting System

=> Recently, many PSCOs ask to operate Local Fire fighting system for M/E

- Fire Isolating Valve Condition(On deck or Shut-off Valve)
- Quick Closing Valve Operation
- Aux Boiler Alarm(Flame Failure and Lowest Level Shut Down)
- Fire Detection System
- Pollution Prevention Equipment

Survey Team

Tel: +82 70 8799 8212/8213/8208

E-mail: psc@krs.co.kr

### General Manager of Survey Team

#### Disclaimer

Although all possible efforts have been made to ensure correctness and completeness of the contents contained in this information service, the Korean Register of Shipping is not responsible for any errors or omissions made herein, nor held liable for any actions taken by any party as a result of information retrieved from this information service.